

MAN LOSES LEG

PLANT OPERATOR LEFT MACHINE RUNNING

Operator got into his seat in a machine that had been left idling and engaged the dead man's control before he was settled in his seat.

His jacket caught the control lever and the bucket moved, trapping an operative's leg between the bucket and machine track. The operative lost his leg.

Think about "what could go wrong" if you don't engage the dead man or get out of the seat and leave the machine running.

The Lanyard system is being rolled out to all sites:

YOU MUST USE IT and FOLLOW THE BELOW RULES.

ON CCL SLEWS / ROLLERS and DUMPERS **PLANT OPERATORS MUST NOT:**

- Engage the DEAD MAN until you are settled in your seat
- Rise from your seat for any reason without disengaging the DEAD MAN control
- Should you leave your cab, the machine must be turned off and the key removed (including when climbing down and standing next to the machine)

Think Safe, Work Safe, Stay Safe.